

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
PA.
31-MTUN,
1-A-

HAER No. PA-242-A

Harbison-Walker Refractories Company,
Engine Repair House
West end of Shirley Street
Mount Union
Huntingdon County
Pennsylvania

Jet Lowe, Photographer, May 1989

- | | |
|------------|---|
| PA-242-A-1 | GENERAL VIEW FROM NORTH SIDE OF RIVER LOOKING SOUTHEAST
OVER ENGINE REPAIR HOUSE, DINKY LEVELS VISIBLE IN DISTANCE |
| PA-242-A-2 | PERSPECTIVE VIEW OF SOUTH SIDE AND WEST END OF ENGINE
REPAIR HOUSE, HARBISON-WALKER QUARRY |
| PA-242-A-3 | VIEW OF EAST END OF ENGINE REPAIR HOUSE |
| PA-242-A-4 | INTERIOR VIEW OF REPAIR HOUSE LOOKING OUT EAST END |

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
PA
31-MTUN,
IA-

ADDENDUM TO
HARBISON-WALKER REFRACTORIES COMPANY,
ENGINE REPAIR HOUSE
West end of Shirley Street
Mount Union
Huntingdon County
Pennsylvania

HAER No. PA-242-A

(P. 2)

PA-242-A-1 through PA-242-A-⁴~~5~~ were previously transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jet Lowe, Photographer, May 1989

PA-242-A-⁵~~6~~ (CT) GENERAL VIEW FROM NORTH SIDE OF RIVER LOOKING SOUTHEAST OVER
ENGINE REPAIR HOUSE, DINKY LEVELS VISIBLE IN DISTANCE